

Yukon Utilities Board

September 19, 2012

John Maissan
Leading Edge Projects Inc.
219 Falcon Drive
Whitehorse, Yukon Y1A 0A2

Dear Mr. Maissan:

**Re YEC 2012 General Rate Application Proceeding
IRs re YEC 2011-2030 Resource Plan**

The Yukon Utilities Board is in receipt of your correspondence dated September 17 and September 19, 2012 (attached) regarding the Yukon Energy Corporation (YEC) 2012 GRA proceeding and Information Requests (IRs) related to YEC's 2011-2030 Resource Plan.

The GRA proceeding schedule has been set according to Board Order 2012-08 and it is not open to a party to unilaterally change or add to the process. As you are aware, all Parties have been provided two opportunities to ask IRs of YEC. Any further questions, if relevant, may be asked of YEC witnesses during the upcoming oral hearing scheduled for November 12-14, 2012. Therefore, no third round of information requests is permitted.

Furthermore, the Board, through Board Order 2012-08, stated the following:

3. The Board notes that YEC did not comply with the second direction given in Board Order 2012-07:

... that responses to IRs should be cross-referenced wherever there are references to another IR or there is duplication in a response to more than one IR. The Board directs all Parties, when providing a response to an IR which refers to the answer in another IR, to identify the cross-referenced IR and to include a copy of the response to the cross-referenced IR.

.../2

Page 2

For instance, the Board notes the response to YUB-YEC-1-2(a) where there is a reference to CW-YEC-1-1(a). A copy of the response to CW-YEC-1-1(a) is not included in the response to YUB-YEC-1-2(a). Similar examples include references contained in YUB-YEC-5(a & b), CW-YEC-1-6(a), LE-YEC-1-3(a), UCG-YEC-1-3(c), YCS-YEC-1-3, and YECL-YEC-1-8(a). The Board does not consider this an exhaustive list, and it expects YEC to provide cross-references wherever it is appropriate to do so given its IR Responses in this proceeding.

Subsequent to that Order, the Board noted that links to the referenced IRs were present in the consolidated IR responses that were available for download from the company website. The error occurred because the referenced IR responses were not highlighted in the PDF version of the responses but the links were operational.

Sincerely,

A handwritten signature in black ink, appearing to read 'Bruce McLennan', with a long horizontal flourish extending to the right.

Bruce McLennan
Chair

c. All Parties
Attach. (2)