



Outage / Disturbance Report 2021

Outage/Disturbance Report January 2021					
Date	Code	Comments	Location	# of Customers Affected	Duration Hrs
Jan 18, 2021	604 (Ice/Icing)	Windy and wet snow at the time of the outage. Also lots of frost built up on power lines. Possible line slap.	Dawson (Feeder 1)	429	0.07
			Dawson (Feeder 2)	510	0.08
			Dawson S250-52-2 (Hunker Feeder)	448	0.02
			L177 not including Dawson City	3	0.01
Jan 25, 2021	604 (Ice/Icing)	S258-52-2 Tripped. Breaker closed and held on first attempt. Suspect heavy frost/ice buildup on power lines.	L250 (S258-52-2 to Keno)	3	0.01

Outage/Disturbance Report February 2021					
Date	Code	Comments	Location	# of Customers Affected	Duration Hrs
Feb 23, 2021	108 (Other Scheduled)	Tree was dropped on line while Ace was brushing ROW, resulted in a planned outage to remove tree. No unplanned outage caused as a result of the tree landing on the power line. This outage affected Alexco Mine.	L250 (S258-52-2 to Keno)	3	2.00

Outage/Disturbance Report March 2021					
Date	Code	Comments	Location	# of Customers Affected	Duration Hrs
Mar 25, 2021	201 (Transmission Planned)	Planned power outage under GOI 21-203. Install Tap from Feeder 1 in Dawson.	Dawson (Feeder 1)	429	2.68